

“Probes_Manager_Setup.exe” software history 3.06

Here are reported only the last 3 releases, the complete release history is available on request

Ver.	Date	Applied Modifications
3.06	16/01/2024	– Probes manager.exe rel. 3.07
3.05	14/12/2023	– Probes manager.exe rel. 3.06 – LR01 Firmware 1.19
3.04	21/11/2023	– Probes manager.exe rel. 3.05 – LR01 Firmware 1.17 – LR01AMCETHTool.exe rel 1.00

Probes_Manager.exe		
Ver.	Date	Applied Modifications
3.06	16/01/2024	– Minor bug fix. Fixed bug in plot mode using EP60X models
3.05	21/11/2023	– With SMARTSAMC, Ethernet communication implemented – Minor bug fixes
3.04	27/10/2023	– With LR01 and EHP2B probes, implemented changes relating to the new management of frequency correction

Firmware LR01		
Ver.	Date	Applied Modifications
1.19	11/12/2023	– Minor bug fixed
1.17	24/11/2023	– Minor bug fixed
1.15	29/09/2023	– Minor bug fixed – Implemented linear/quadratic weighting for EHP-2B

LR01AMCEthTool.exe		
Ver.	Date	Applied Modifications
1.0	27/11/2023	– First release